



# SAFETY & LIGHTING SURVEYS





# HOW SAFE ARE YOUR ATMS?

## ARE YOUR BRANCHES PROVIDING SUFFICIENT LIGHT FOR THE SAFETY OF YOUR CUSTOMERS AT NIGHT?

Many states have ATM lighting laws and regulations. Not only is it a legal requirement, but it can also help lower crime rates. Most states require a safety & lighting check around an ATM to prove that it meets various “Lumens” or brightness values to ensure enough light to give your customer a safe environment to access an ATM at night. All of our technicians are trained and certified to provide detailed lighting and safety surveys.

# SAFETY SURVEYS

Stickydata provides safety surveys with regular checkups. Mirrors, cameras and landscaping components in the ATM environment are checked. Have seasonal changes affected landscaping? Detailed reports contain photos that show all angles and areas of concern.



**SAFETY**  
**Passed**

**Reasons:**

Is there a security notice posted near the ATM?  
**YES**

Is there overgrown landscaping near the ATM or ATM entrance?  
**NO**

Are mirrors installed on the ATM?  
**YES**

Are there surveillance cameras monitoring the ATM area?  
**YES**

**PHOTOGRAPHS WALL LABEL AREA**

**RECEIPT**

**ATM**

**SURVEILLANCE CAMERA**

**SURVEY MEASUREMENTS**

**PASSED**



# LIGHTING SURVEYS



**FAILED**



### LIGHTING Failed

**Reasons:**

- The Illumination at or within 50 feet of the ATM or ATM entrance is less than 2 foot candles.
- The Illumination at or within 50 feet of the ATM or ATM entrance is less than 2 foot candles.
- The Illumination at or within 50 feet of the ATM or ATM entrance is less than 2 foot candles.
- Within the parking area the Illumination at or within 60 feet of the ATM or ATM entrance is less than 1 foot candle.

**Light Fix Not Working**

Item No.	Type
1	Street Light

**Light Replacement: None**

Presence of (L) or (R) required. Light Fix Replaces as Part of this Survey.



LIGHT METER ASSET NUMBER      LIGHTING DIAGRAM





All ATM area lighting is checked for proper functionality. Deficiencies are identified, photographed and everything uploads seamlessly into Stickydata for easy management.

Illumination values determined from the ATM face to 60' out in all directions using calibrated light meters. Non-working light fixtures are documented. Site diagrams, overview drawings and comprehensive photos show problem areas and contextualize the data. The report is simple and concise, clearly highlighting deficiencies.

# FULL SERVICE SAFETY & LIGHTING SURVEYS

## SAFETY & LIGHTING SURVEY COMPARISONS

SERVICES & CHECKS PERFORMED	LIGHTING CHECK WITH SAFETY	NIGHTTIME LIGHTING CHECK WITH SAFETY
Business Hours Check	√	√
Can the ATM Lighting be turned off by the Public?	√	√
What Lights are out in the survey area	√	√
Any Lights replaced (if contracted to do so.)	√	√
Do Lights work after replacing	√	√
Interior Accessibility, door security/locking devices/card reader check	√	√
Safe, unobstructed view of ATM check	√	√
Illumination checks (in Foot Candles)	-	√
Measure lumens in a radius of 5-60 Feet around ATM	-	√
Obstacles to lighting identified	-	√
Corners identified	-	√
Dark areas identified	-	√
Comparison to measurements to State Laws for compliance.	-	√
PDF Report provided showing Pass/Fail based on state laws	-	√



# NIGHTTIME LIGHTING SURVEY CAD DRAWINGS

All Nighttime Lighting Surveys include a detailed CAD drawing of the area indicating the area and light brightness. All lights are visually documented, showing burned out or low light issues. Also, Safety areas are identified so that they can be addressed. These reports are shown in Stickydata and as PDFs if required by a regulative entity.



# HIGHLY TRAINED TECHNICIANS

OUR HIGHLY TRAINED TECHNICIANS ARE PROFESSIONALLY CERTIFIED AND ALWAYS  
WORK WITHIN THE REGULATIONS OF LOCAL AND STATE JURISDICTIONS.

**CONTACT US TODAY TO LEARN MORE**  
**1-800-550-5087**



Questions?

**CONTACT US TODAY!**



1-800-550-5087  
sales@atmusa.com  
atmusa.com

